

**Arkansas Department of Environmental Quality
Hazardous Waste Division
Technical Branch
Trip Report**


Project	Former Cedar Chemical Facility
Location	West Helena, AR
Date	Thursday, August 1, 2013
Time	day trip
Reason	Observe Site Conditions
ADEQ personnel	Clay McDaniel CM
Facility personnel	Gary Hill – Harcross employee
Activity Summary	Gary accompanied with me as I inspected the facility
Action Items Summary	<p>The soil pile from excavation of the sump is still located on the former Unit 4 foundation (see photo's 1 & 2). It has been 519 days between when it was 1st discovered (ADEQ site visit on 3/1/2012) and this site visit. Bi-weekly status updates for the waste pile were requested in ADEQ letter dated 05/31/2012, but no updates have been submitted.</p> <p>Identified drum labeled hazardous waste (see photo # 3)</p> <p>The IDW (18 five-gallon buckets of purge water from the July 2010 sampling event, shown in photo #4) has not been disposed of. ADEQ letter dated 8/28/2012 provided procedures for proper disposal.</p>
Follow-Up	


Route to:

ADEQ personnel review	Initials	Date
Jim Rigg	JWR	8/6/13
Annette Cusher	AC	8/6/13
Jay Rich	JR	8-8-13

Enclosure: Photo Log

Arkansas Department of Environmental Quality
Official Photograph Log

Soil Pile from Sump Excavation (located on the former Unit 4 footprint)	
Photo # 1	Photographer: Clay McDaniel, ADEQ <i>CM</i>
Date: August 1, 2013	Witness: Gary Hill, Harcross
	

Soil Pile from Sump Excavation	
Photo # 2	Photographer: Clay McDaniel, ADEQ <i>CM</i>
Date: August 1, 2013	Witness: Gary Hill, Harcross
	

Arkansas Department of Environmental Quality
Official Photograph Log

55-Gallon Drum Labeled Hazardous Waste	
Photo # 3	Photographer: Clay McDaniel, ADEQ <i>CM</i>
Date: August 1, 2013	Witness: Gary Hill, Harcross

Investigative Derived Waste (purged groundwater)	
Photo # 4	Photographer: Clay McDaniel, ADEQ <i>CM</i>
Date: August 1, 2013	Witness: Gary Hill, Harcross